

**AHERA PERIODIC SURVEILLANCE FORM
Management Plan Document**

Building Name: Hillsboro Elementary School
37110 Charles Town Pike, Purcellville, Virginia
Bulletin Board +

Type of ACBM/Location: Chalkboard mastic (assumed asbestos-containing):

- Assumed behind all chalkboards throughout building

Status: (Choose One)

1. Removed
2. Encapsulated
3. Enclosed
4. Other: Placed in an O&M Program

Assessment of Material:

1. Physical Damage (Yes or No)
2. Water Damage (Yes or No)
3. Delamination (Yes or No)
4. Located in Air Plenum (Yes or No)
5. Other: *Inaccessible*

Degree of Accessibility: High 1 2 3 4 5 6 7 8 9 10 Low

Degree of Activity Near Material: High 1 2 3 4 5 6 7 8 9 10 Low

Other Observations (Including condition of encapsulant or enclosure):

Many appear nailed or screwed in but mastic may be supplemented.

Inspected by:

Michael Sullivan

Date:


8/22/18

Signed:

MKS Sullivan

Homogenous Area ID Number:

FRNK/HELVESTON
COTTAGE #1
ART/MUSIC



AHERA PERIODIC SURVEILLANCE FORM
Management Plan Document

Building Name: Hillsboro Elementary School
37110 Charles Town Pike, Purcellville, Virginia

Type of ACBM/Location: Pipe Insulation

- Assumed behind plaster walls, ceilings, and inside pipe chases

Status: (Choose One)

1. Removed
2. Encapsulated
- ③ 3. Enclosed
4. Other: Placed in an O&M Program

Assessment of Material:

1. Physical Damage (Yes or No)
2. Water Damage (Yes or No)
3. Delamination (Yes or No)
4. Located in Air Plenum (Yes or No)
- ⑤ 5. Other: *Inaccessible*

Degree of Accessibility: High 1 2 3 4 5 6 7 8 9 10 Low

Degree of Activity Near Material: High 1 2 3 4 5 6 7 8 9 10 Low

Other Observations (Including condition of encapsulant or enclosure):


Inspected by: *Michael Sullivan*

Date: *8/22/18*

Signed: *Mike Sullivan*

Homogenous Area ID Number:

FINK/HELVESTON
COTTAGE #1
ART/MUSIC



**AHERA PERIODIC SURVEILLANCE FORM
Management Plan Document**

Building Name: Hillsboro Elementary School
37110 Charles Town Pike, Purcellville, Virginia

Type of ACBM/Location: Fire door (assumed asbestos-containing):

- Main office storage room

Status: (Choose One)

1. Removed
2. Encapsulated
3. Enclosed
- 4. Other: Placed in an O&M Program**

Assessment of Material:

1. Physical Damage (Yes or No)
2. Water Damage (Yes or No)
3. Delamination (Yes or No)
4. Located in Air Plenum (Yes or No)
5. Other:

Degree of Accessibility: High 1 2 3 4 5 6 7 8 9 10 Low

Degree of Activity Near Material: High 1 2 3 4 5 6 7 8 9 10 Low

Other Observations (Including condition of encapsulant or enclosure):

Inspected by: Michael Sullivan

Date: 8/22/18

Signed: *Michael Sullivan*

Homogenous Area ID Number: (F.2) M04

